



DATE	REVISION	DESCRIPTION
02/05/08	DMB	R14 CHANGE TB LEGENDS
06/02/05	DMB	R13 CHANGE WIRING DIAGRAM AND BUS ENLARGE DWG
02/26/03	DMB	R12 CHANGE WIRING TO HOURS
02/17/03	DMB	R11 CHANGE NOTE & RELAY WIRING
12/10/02	DMB	R10 CHANGE RELAY WIRING
11/06/02	DMB	R9 TO L1
12/18/01	DMB	R8 ALARM RELAY
09/16/01	DB	R7 CORRECT WIRING
02/20/01	DMB	R6 ADD 27V DIAGRAM
9/1/00	DMB	R5 CORRECT OPTION CHART

  

DATE	REVISION	DESCRIPTION
11/14/95	DSCN:TKM	WIRING DIAGRAM
11/14/95	APFD:JHALL	CAT. CM-1-48N4 OR CONTINUITY ALARM PANEL
02/25/95	DSCN:TKM	PROCESS CIRCUITS CLASS 319
02/25/95	APFD:JHALL	DOC# GD-318.DWG
02/25/95	DSCN:TKM	SC: NONE
02/25/95	APFD:JHALL	SC: NONE

  

DATE	REVISION	DESCRIPTION
02/25/95	DSCN:TKM	WIRING DIAGRAM
02/25/95	APFD:JHALL	CAT. CM-1-48N4 OR CONTINUITY ALARM PANEL
02/25/95	DSCN:TKM	PROCESS CIRCUITS CLASS 319
02/25/95	APFD:JHALL	DOC# GD-318.DWG
02/25/95	DSCN:TKM	SC: NONE
02/25/95	APFD:JHALL	SC: NONE